



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office, 3190 - 160th Ave S.E. • Bellevue, Washington 98008-5452 • (206) 649-7000


**Professional Engineer's Statement
Everett Smelter Cleanup, 2000-2001**

Sampling and soil remediation were carried out at the following homes within the Everett Smelter Site during the years 2000 and 2001:

| <u>Address</u> | <u>Owner</u> |
|-------------------------------------|-------------------|
| Muriel Jones | 110 Bridgeway |
| Andrew Michels | 235 Bridgeway |
| Jeanette Mempa | 236 Bridgeway |
| Thomas, Christine & Ronnie | 240 Bridgeway |
| Martha Watkins | 244 Bridgeway |
| Joanne Felmer | 2803 Medora Way |
| Terry Tavares & Linda Guy-Tavares | 2811 Medora Way |
| Duane & Edna Rapelje | 2817 Medora Way |
| Dave & Rene Goodrich | 2818 Medora Way |
| Ron & Bonnie Sylvester | 2830 Medora Way |
| Anh Black | 528 Hawthorne |
| Steve & Sherrie Wamba | 415 Legion Drive |
| Gary & Darlene Bunger & Sandra Kane | 112 Skyline Drive |
| Michael Paeth | 116 Skyline Drive |
| Randy Hall | 212 Skyline Drive |
| Willy Pompey | 215 Skyline Drive |
| Dorothy Larson | 218 Skyline Drive |
| Bob & Peggy Redline | 221 Skyline Drive |
| Michael & Sheila Crehan | 222 Skyline Drive |
| Kurt Bertilson | 230 Skyline Drive |
| Louise Hiller | 302 Skyline Drive |
| Margie Hogle | 303 Skyline Drive |
| Fred Brown | 307 Skyline Drive |
| Jackie Robinett | 308 Skyline Drive |
| Al Vandenbosch | 316 Skyline Drive |
| Al Sorenson | 320 Skyline Drive |
| Jo Newland | 323 Skyline Drive |
| John & Christina Bull | 328 Skyline Drive |

Based on the results of testing and inspections, it is my opinion that the soil remediation carried out at these homes was performed in substantial compliance with the plans, specifications, and related documents governing the work.

Remediation work remaining to be done at these homes includes evaluation of crawl space data and addressing crawl spaces as necessary and carpet and duct cleaning. Some plant replacement also remains to be done and will be done this Spring.



**Washington Department of Ecology
Everett Smelter Site
2000-2001 Cleanup**

Details of Cleanup Activities

The Department of Ecology (Ecology) targeted the cleanup of the yards of 24 homes, within the Everett Smelter Site, during the 2000-2001 biennium. The cleanup was conducted according to the *Everett Smelter Site: Integrated Final Cleanup Action Plan and Final Environmental Impact Statement for the Upland Area*.

This report describes the cleanup actions that were conducted, what arsenic-contaminated soil was removed and where it remains, for the following location:

Property Owner: Louise Hiller

Address:
302 Skyline Drive
Everett, WA 98201

Snohomish County
State of Washington
Tax Parcel No. # 5203-000-012-0000

This property was divided by Ecology into two Decision Units, A and B, as shown on the attached map, for purposes of pre-cleanup sampling and decision-making regarding the depth to which excavation was required. The following is a summary of the work done in the remediation of the property within each of the decision units.

Decision Unit: A

Results of pre-cleanup sampling indicated 24 inches of soil were to be excavated from within this decision unit. Attachment B shows that below 24 inches, results of composite sample analyses are below the remediation level of 150 parts per million (ppm). However, because the soil below 24 inches contains arsenic levels above the cleanup level of 20 ppm, a geofabric marker was placed.

Field measurements by the Ecology on-site coordinator confirmed that soil was removed to a depth of 24 inches except the excavation was sloped 1:1 away from the house foundation, the curb along Skyline Drive, the driveway, and the front walk in order to

1. The first part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the... ()

2. The second part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the...

The third part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the... ()

The fourth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the...

The fifth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the...

The sixth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the... ()

The seventh part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the...

The eighth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the...

The ninth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the... ()

The tenth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the...

The eleventh part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the... ()

The twelfth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the... ()

The thirteenth part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the... ()

maintain the structural integrity of those structures. At the owner's request, the azalea at the northeast corner of the front steps was left in place, as was the bush at the west end of the driveway. Soil was removed from the planters along the house. A block retaining-wall was constructed along the north side of the property in order to re-establish the original grade of the yard. After excavation of the decision unit was completed, a geofabric marker was placed, and backfilling with clean backfill material was carried out, as described in the *Specifications for Everett Residential Soil Remediation*. Topsoil was then placed, and new sod was planted.

Decision Unit: B

Results of pre-cleanup sampling indicated 24 inches of soil were to be excavated from within this decision unit. Attachment B shows that below 24 inches, results of composite sample analyses are below the remediation level of 150 ppm. Because the soil below 24 inches contains arsenic levels below the cleanup level of 20 ppm, a geofabric marker was not placed.


Field measurements by the Ecology on-site coordinator confirmed that soil was removed to a depth of 24 inches. Exceptions were along the foundation of the house and the sidewalk, where the excavation was sloped 1:1 in order to maintain the structural integrity of those structures, and beneath the stand for the above-ground heating oil tank at the west side of the house. A concrete sump, with unknown purpose or function, was encountered at the west side of the house; this was left in place. A block retaining-wall was constructed along the north side of the property in order to re-establish the original grade of the yard. After completing the excavation, backfilling with clean backfill material was carried out, as described in the *Specifications for Everett Residential Soil Remediation*. Topsoil was then placed, and new sod was planted.




Al Armstrong
Washington Department of Ecology

December 18, 2000

Note: As of December 18, 2000, replacement trees or bushes had not been planted. This was completed on January 15, 2001.



Dan Cargill
Washington Department of Ecology




Date

ATA:aa

Attachments: Site Map
Graphs of Arsenic Concentration vs. Depth (1 page)
Graph Explanation

Note: If the attachments listed above do not accompany this document, copies may be obtained from Ecology. Please contact Sally Perkins, Central Files of Ecology's Northwest Regional Office (NWRO), at (425) 649-7190 for information on obtaining copies.

cc: Ecology Central Files, NWRO
Mary Sue Wilson, Assistant Attorney General
Mike Young, Snohomish Health District
City of Everett
Snohomish PUD
Northeast Everett Community Organization
Northwest Everett Neighborhood Association



302 Skyline

Everett Smelter Homesite Cleanup

Source: Snohomish Health District



Not to scale

- Landscape Samples
- DU Samples



