



STATE OF WASHINGTON  
DEPARTMENT OF ECOLOGY

Northwest Regional Office, 3190 - 160th Ave S.E. • Bellevue, Washington 98008-5452 • (206) 649-7000


**Professional Engineer's Statement  
Everett Smelter Cleanup, 2000-2001**

Sampling and soil remediation were carried out at the following homes within the Everett Smelter Site during the years 2000 and 2001:

<u>Address</u>	<u>Owner</u>
Muriel Jones	110 Bridgeway
Andrew Michels	235 Bridgeway
Jeanette Mempa	236 Bridgeway
Thomas, Christine & Ronnie	240 Bridgeway
Martha Watkins	244 Bridgeway
Joanne Felmer	2803 Medora Way
Terry Tavares & Linda Guy-Tavares	2811 Medora Way
Duane & Edna Rapelje	2817 Medora Way
Dave & Rene Goodrich	2818 Medora Way
Ron & Bonnie Sylvester	2830 Medora Way
Anh Black	528 Hawthorne
Steve & Sherrie Wamba	415 Legion Drive
Gary & Darlene Bunger & Sandra Kane	112 Skyline Drive
Michael Paeth	116 Skyline Drive
Randy Hall	212 Skyline Drive
Willy Pompey	215 Skyline Drive
Dorothy Larson	218 Skyline Drive
Bob & Peggy Redline	221 Skyline Drive
Michael & Sheila Crehan	222 Skyline Drive
Kurt Bertilson	230 Skyline Drive
Louise Hiller	302 Skyline Drive
Margie Hogle	303 Skyline Drive
Fred Brown	307 Skyline Drive
Jackie Robinett	308 Skyline Drive
Al Vandebosch	316 Skyline Drive
Al Sorenson	320 Skyline Drive
Jo Newland	323 Skyline Drive
John & Christina Bull	328 Skyline Drive

Based on the results of testing and inspections, it is my opinion that the soil remediation carried out at these homes was performed in substantial compliance with the plans, specifications, and related documents governing the work.

Remediation work remaining to be done at these homes includes evaluation of crawl space data and addressing crawl spaces as necessary and carpet and duct cleaning. Some plant replacement also remains to be done and will be done this Spring.



**Washington Department of Ecology  
Everett Smelter Site  
2000-2001 Cleanup**

**Details of Cleanup Activities**

The Department of Ecology (Ecology) targeted the cleanup of the yards of 24 homes, within the Everett Smelter Site, during the 2000-2001 biennium. The cleanup was conducted according to the *Everett Smelter Site: Integrated Final Cleanup Action Plan and Final Environmental Impact Statement for the Upland Area*.

This report describes the cleanup actions that were conducted, what arsenic-contaminated soil was removed and where it remains, for the following location:

Property Owner: Joann Newland

Address:  
323 Skyline Drive  
Everett, WA 98201

Snohomish County  
State of Washington  
Tax Parcel No. # 5203-000-056-0007

This property was divided by Ecology into two Decision Units, A and B, as shown on the attached map, for purposes of pre-cleanup sampling and decision-making regarding the depth to which excavation was required. The following is a summary of the work done in the remediation of the property within each of the decision units.

Decision Unit: A

Results of pre-cleanup sampling indicated 18 inches of soil were to be excavated from within this decision unit. Attachment B shows that below 18 inches, results of composite sample analyses are below the remediation levels of 60 and 150 ppm. Because the soil below 18 inches contains arsenic levels above the cleanup level of 20 ppm, a geofabric marker was placed.

Field measurements by the Ecology on-site coordinator confirmed that soil was removed to a depth of 18 inches. Exceptions were along the foundation of the house, front walk, driveway, and the street curb, where the excavation was sloped 1:1 in order to maintain

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes that this is crucial for ensuring transparency and accountability in the organization's operations.

### 2. Financial Reporting

The second part of the document details the requirements for financial reporting. It outlines the specific information that must be included in the reports, such as income statements, balance sheets, and cash flow statements. It also discusses the frequency and format of these reports.

It further explains the role of the accounting department in preparing these reports and the importance of timely submission to the relevant authorities.

### 3. Internal Controls

The third part of the document focuses on internal controls. It describes the various mechanisms in place to prevent and detect errors and fraud within the organization. This includes segregation of duties, authorization procedures, and regular audits.

The document also highlights the importance of a strong internal control system for maintaining the integrity of the organization's financial data and ensuring compliance with applicable laws and regulations.

In conclusion, the document stresses that effective financial management and reporting are essential for the long-term success and sustainability of any organization. It encourages all stakeholders to work together to ensure the highest standards of accuracy and transparency in all financial activities.

### 4. Compliance


The final part of the document discusses the organization's commitment to compliance with all applicable laws and regulations. It outlines the specific measures in place to ensure that the organization remains up-to-date with the latest regulatory requirements and that all activities are conducted in a lawful and ethical manner.

the structural integrity of those structures. All plants, bushes, shrubs, and trees were removed. After completing the excavation, a geofabric marker was placed, and backfilling with clean backfill material was carried out, as described in the *Specifications for Everett Residential Soil Remediation*. Topsoil was then placed, and new sod was planted. No replacement plants were required for this property.

Decision Unit: B

Results of pre-cleanup sampling indicated 18 inches of soil were to be excavated from within this decision unit. Attachment B shows that below 18 inches, results of composite sample analyses are below the remediation levels of 60 and 150 ppm. Because the soil below 18 inches contains arsenic levels above the cleanup level of 20 ppm, a geofabric marker was placed.

Field measurements by the Ecology on-site coordinator confirmed that soil was removed to a depth of 18 inches. Exceptions were along the foundation of the house and sidewalk, where the excavation was sloped 1:1 in order to maintain the structural integrity of those structures. All plants, bushes, shrubs, and trees were removed. After completing the excavation, a geofabric marker was placed, and backfilling with clean backfill material was carried out, as described in the *Specifications for Everett Residential Soil Remediation*. Topsoil was then placed, and new sod was planted. A portion of the property, at the east side of the house, was finished with crushed rock. No replacement plants were required for this property.

  
\_\_\_\_\_  
Al Armstrong  
Washington Department of Ecology

December 18, 2000

ATA:aa

Attachments: Site Map  
Graphs of Arsenic Concentration vs. Depth (1 page)  
Graph Explanation

Note: If the attachments listed above do not accompany this document, copies may be obtained from Ecology. Please contact Sally Perkins, Central Files of Ecology's

...the ... of ...  
...the ... of ...  
...the ... of ...

...the ... of ...  
...the ... of ...  
...the ... of ...

...the ... of ...  
...the ... of ...  
...the ... of ...  
...the ... of ...  
...the ... of ...


...the ... of ...  
...the ... of ...

...the ... of ...  
...the ... of ...

Northwest Regional Office (NWRO), at (425) 649-7190 for information on obtaining copies.

cc: Ecology Central Files, NWRO  
Mary Sue Wilson, Assistant Attorney General  
Mike Young, Snohomish Health District  
City of Everett  
Snohomish PUD  
Northeast Everett Community Organization  
Northwest Everett Neighborhood Association





# 323 Skyline

Everett Smelter Homesite Cleanup

Source: Snohomish Health District



Not to scale

- Crawlspace Samples
- DU Samples



