



©2009 Google™



Legend	
● Manhole	— Curb
■ Catch basin	■ Stabilized/controlled upland area
□ Outfall	■ Enhanced vegetation on vegetated bank area
	■ Stabilized/armored intertidal bank area

Note: aerial photo view with 80° heading and 18° tilt. North is thus approximately to the left, and locations of parcel boundaries, paved areas, and storm drain network features are approximate.

Figure 6. Western Parcel after implementation of recommended alternatives