

Appendix D-3

Hart Crowser 1989b: Report of Environmental Assessment—Parcel D, Soil and Groundwater Conditions, Evergreen Marine Leasing Property

#3

RECEIVED

JAN 05 1993

DEPT. OF ECOLOGY



HARTCROWSER


Earth and Environmental Technologies

*Environmental Assessment
- Parcel D
Soil and Groundwater Conditions
Evergreen Marine Leasing Property
Seattle, Washington*



*Prepared for
Evergreen Marine Leasing*

*July 20, 1989
J-2183-09*


Site and Exploration Plan



Generalized Subsurface Profiles A-A' and B-B'




HC-9 Boring Number
Boring Location



Groundwater Elevation Contour Map

High Tide



Approximate Direction of Groundwater Flow
 Influx Surface Water
 Groundwater Elevation Contour in Feet
 HC-1 Boring/Monitoring Well Location and Number
 5.24 Spot Groundwater Elevation in Feet
 Note: Base map prepared from Sanborn Fire Insurance Maps dated 1950.

DUWAMISH WATERWAY

Groundwater Elevation Contour Map

Low Tide

