

**The Department of Ecology's Response to:
Bud Leber – Kaiser Aluminum (Comment 05)**

A review of airphotos and a system description confirms the identified waterway as “source” water and not receiving water. Listing ID 42355 has been inactivated.