Appendix D-4

Landau 1990: Environmental Site Assessment, First Interstate Bank of Washington Property

IC#162

Final Report

Environmental Site Assessment
First Interstate Bank of Washington Property
7400 8th Avenue South and
7343 East Marginal Way South
Seattle, Washington

June 8, 1990

Volume I of II

Prepared for

Boeing Environmental Affairs
Seattle, Washington

Prepared by

Landau Associates, Inc.
P.O. Box 1029
Edmonds, WA 98020-9129

EML 90 - 004



Source: Dodds Engineers, Inc. (January 1989).

LANDAU ASSOCIATES, INC.

Locations of Soil Borings and Surface Soil Samples

Figure 4-1



Source: Dodds Engineers, Inc. (January 1989).

LANDAU ASSOCIATES, INC.

Locations of Monitoring Wells

Figure 4-2



Source: Dodds Engineers, Inc. (January 1989).

LANDAU ASSOCIATES, INC.

Locations of Geologic Cross Sections

Figure 4-3



LANDAU ASSOCIATES, INC.

Geologic Cross Sections A-A' and B-B'
Parcels D and F

Figure 4-4



LANDAU ASSOCIATES, INC.

Geologic Cross Sections C-C' and D-D'
Parcel E

Figure 4-5



Source: Dodds Engineers, Inc. (January 1989).

LANDAU ASSOCIATES, INC.

Ground Water Elevation Contour Map - High Tide

Figure 4-6



Source: Dodds Engineers, Inc. (January 1989).

LANDAU ASSOCIATES, INC.

Ground Water Elevation Contour Map - Low Tide

Figure 4-7