

GPS01003006-20.dwg 3/6/02

ANCHOR ENVIRONMENTAL, L.L.C.

Figure 3
Total Cap/Habitat Layer Thickness - October 2001
Log Pond Cleanup and Habitat Restoration