

I:\CAD\Jobs\000030-GP Log Pond\02003001-Year2\GP-02003001-04-xxx.dwg Fig3

Dec 03, 2002 11:03am rchao

ANCHOR ENVIRONMENTAL, L.L.C.

Figure 3
Change in Log Pond Surface
7 Months after Construction - October 2001