

Figure ES-4: Conceptual Sketch of Conditions in the Upland Area of the Everett Smelter Site Before and After Cleanup. (Same as Figure 9-1)