Photo # 49: Unknown material seep in area of waste drums

Photo # 50: Oil sheen, discolored soils with noticeable petroleum smell in area of drum waste.

Photo # 51: Same as previous picture



Photo # 52: Waste pile under Building at EAA-2

Photo # 53: Unidentified material deposit in channel bottom at EAA-2

Photo # 54: Close-up of unidentified deposit

Photo # 55: Small seep in area of waste pile. Soils in this area smell of petroleum.

Photo # 56: Unknown material discharge at piling base near the waste piles at EAA-2