Figure 4-4.
Potential Fixed Sources of Dioxins/Furans in Port Angeles
Rayonier Mill Off-Property Soil Dioxin Study
Port Angeles, WA

Legend

Potential Dioxins/Furans Sources

- Current Boiler
- Current Crematoria
- Current Diesel Boiler
- Current Hog Boiler
- Current Propane Boiler
- Historic Hog Boiler
- Historic medical waste incinerator
- River
- Highway
- Arterial or Collector Road
- Road
- Port Angeles City Limits

ecology and environment, inc.
International Specialists in the Environment

HERRERA ENVIRONMENTAL CONSULTANTS

0 1,250 2,500 5,000 feet

Coordinates: Washington State Plane South
NAD 83 (feet)
Aerial: USDA, 2006

N

Produced By: GIS (JAS)
Project:
K:/Projects/06-03386-006/Projects/Dioxin and Furan Sources.mxd (06/06/2008)