

GPS01003006-21.dwg 3/6/02

ANCHOR ENVIRONMENTAL, L.L.C.

Figure 2
Log Pond Interim Action Cleanup and Habitat Restoration - Cap Thickness
Draft Supplemental EIS - Bellingham Bay Comprehensive Strategy