

13 REFERENCES

- APHA (American Public Health Association), American Water Works Association (AWWA), Water Environment Federation (WEF). 1995. *Standard Methods for the Examination of Water and Wastewater*, 19th Edition, M.A. Franson, Mgn. Ed., American Public Health Association, Washington, D.C.
- ASTM (American Society for Testing and Materials). 1995. *1995 Annual Book of ASTM Standards, Section 11 - Water and Environmental Technology*, Vols. 11.01-11.05, American Society for Testing and Materials, Philadelphia, Pennsylvania.
- AOAC International. 1995. *Official Methods of Analysis of AOAC International*, 16th Edition, Patricia Cunniff, Ed. AOAC International, Arlington, Virginia.
- Bragdon-Cook, K. 1995. *Review of New Scientific Information for SMS Rule Triennial Review: Sediment Management Standards Detection Limits*. Washington State Department of Ecology, Olympia, WA.
- Ecology (Washington State Department of Ecology). 1991a. *Guidelines and Specifications for Preparing Quality Assurance Project Plans*. Publication 91-16, Ecology Environmental Investigations and Laboratory Services Program, Quality Assurance Section, Manchester, Washington.
- Ecology. 1991b. *Sediment Cleanup Standards User Manual (SCUM2)*. Washington State Department of Ecology, Sediment Management Unit, Olympia, WA.
- Ecology. 1995. *Sediment Sampling and Analysis Plan Appendix (to SCUM1 and SCUM2)*. Prepared for Ecology, Sediment Management Unit, Olympia, WA. PTI Environmental Services, Bellevue, WA. This document is currently under review and has not been published.
- Ecology. 1997. *Analytical Methods for Petroleum Hydrocarbons*. Publication No. ECY 97-602. June 1997.
- EPA (U.S. Environmental Protection Agency). 1978. *NEIC Policies and Procedures*. EPA/330/9-78/00IR. Office of Solid Waste and Emergency Response, Washington, D.C.
- EPA. 1980. *Interim Guidelines and Specifications for Preparing Quality Assurance Project Plans*. EPA/QAMS/005/80. Office of Solid Waste and Emergency Response, Washington, D.C.
- EPA. 1982a. *Technical Additions to Methods for Chemical Analysis of Water and Wastes*. EPA 600/4/82-055.
- EPA. 1982b. *Methods for Organic Chemical Analysis of Municipal and Industrial Wastewater*. EPA 600/4-82-057.

- EPA. 1983. Methods for Chemical Analysis of Water and Wastes. EPA-600/4-79-020. U.S. Environmental Protection Agency, Environmental Monitoring and Support Laboratory, Cincinnati, OH. Rev. March 1983.
- EPA. 1984. Technical Additional to Methods for Chemical Analysis of Water and Wastes. EPA 600/4-84-017. U.S. Environmental Protection Agency, Office of Solid Waste and Emergency Response, Washington, D.C.
- EPA. 1989. Guidance on Conducting Remedial Investigations and Feasibility Studies Under CERCLA. EPA/540/6-89/004. Office of Solid Waste and Emergency Response, Washington, D.C.
- EPA. 1993a. Data Quality Objectives Process for Superfund, Interim Final Guidance. EPA/540-R-93-071. Office of Solid Waste and Emergency Response, Washington, D.C.
- EPA. 1993b. EPA Contract Laboratory Program National Functional Guidelines for Organic Data Review. EPA 540/R-94-012. U.S. Environmental Protection Agency, Office of Solid Waste and Emergency Response, Washington D.C.
- EPA. 1994a. Tetra- through Octa-Chlorinated Dioxins and Furans by Isotope Dilution HRGC/HRMS. Method 1613, Revision B. U.S. Environmental Protection Agency, Office of Water, Engineering and Analysis Division (4303). October 1994.
- EPA. 1994b. EPA Contract Laboratory Program National Functional Guidelines for Inorganic Data Review. EPA 540/R-94-013. U.S. Environmental Protection Agency, Office of Solid Waste and Emergency Response, Washington, D.C.
- EPA. 1996a. Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, (SW-846) Third Edition (through Final Update IIB) U.S. Environmental Protection Agency, Office of Solid Waste and Emergency Response, Washington, D.C.
- EPA. 1996b. Inorganic Arsenic in Water by Hydride Generation Quartz Furnace Atomic Absorption. Method 1638. U.S. Environmental Protection Agency, Office of Water, Engineering and Analysis Division (4303). July 1996.
- EPA. 1996c. Determination of Trace Elements in Ambient Waters by Inductively Coupled Plasma – Mass Spectrometry. Method 1638. U.S. Environmental Protection Agency, Office of Water, Engineering and Analysis Division (4303). January 1996.
- EPA. 1998. Rayonier Pulp Mill Expanded Site Inspection, TDD: 97-06-0010. Region 10, Superfund Technical Assessment and Response Team, Seattle, WA. October 1998.
- Freund, J.E. 1973. Modern Elementary Statistics. Fourth Edition. Prentice-Hall, Inc., Englewood Cliffs, New Jersey.

- PSEP (Puget Sound Estuary Program). 1996a. Recommended Guidelines for Measuring Organic Compounds in Puget Sound Water, Sediment and Tissue Samples. Organics chapter. Prepared for U.S. Environmental Protection Agency (Region 10) and Puget Sound Water Quality Authority.
- PSEP. 1996b. Recommended Guidelines for Measuring Metals in Puget Sound Marine Water, Sediment and Tissue Samples. Metals chapter. Prepared for U.S. Environmental Protection Agency (Region 10) and Puget Sound Water Quality Authority.
- PSEP. 1996c. Recommended Quality Assurance and Quality Control Guidelines for the Collection of Environmental Data in Puget Sound. QA/QC chapter. Prepared for U.S. Environmental Protection Agency (Region 10) and Puget Sound Water Quality Authority.
- PSEP. 1997. Recommended Protocols for Measuring Selected Environmental Variables in Puget Sound. Prepared by Washington Department of Ecology, Olympia, Washington for EPA, Region 10, Office of Puget Sound, Seattle, WA. April 1997.
- Zar, J.H. 1974. Biostatistical Analysis. Prentice-Hall, Inc., Englewood Cliffs, New Jersey.

This page intentionally left blank.