

Drawings and Documents
Operating Unit Group 10 – Appendix 6.1
Environmental Risk Assessment Work Plan

The documents listed in the following table are incorporated by reference into this permit and are subject to the requirements set forth in Part I Standard Conditions, Part II General Facility Conditions, and Part III Operating Unit Group 10 Conditions. Upon request, copies of the documents can be viewed at the Nuclear Waste Program Resource Center located at 3100 Port of Benton Blvd. Richland, WA. Appointments for viewing can be scheduled by calling (509) 372-7950.

<i>Appendix</i>	<i>Drawing/Document Number</i>	<i>Description</i>
Appendix 6.1	24590-WTP-RPT-ENS-03-006, Rev 0	Environmental Risk Assessment Work Plan for the Hanford Tank Waste Treatment and Immobilization Plant 07/30/2003 – <u>Replaced with Appendix 6.2</u>
Appendix 6.1.1	24590-RPT-W375-EN00001, Rev. 1	Final Work Plan for Screening Level Risk Assessment for the RPP-WTP 04/28/2000 – <u>Replaced with Appendix 6.2</u>
Appendix 6.1.2	DOE-01-EQD-021	Ecology/EPA Technical Comments on Hanford River Protection Privatization Project Review of BNFL Final Work Plan for Screening Level Risk Assessment for the RPP-WTP 04/28/2000 – <u>Replaced with Appendix 6.2</u>

Source documents (which do not include a "P" in the last set of numbers, e.g. "-P0001," or "-TP001") should be used in conjunction with any document change notices issued against them.

We are currently transitioning from permit documents (which do include a "P" in the last set of numbers) to source documents. At the end of the transition period, permit submittals will contain source documents and will be incorporated into the permit as described in Ecology Publication # 07-05-006 (www.ecy.wa.gov/biblio/nwp.html).

1
2
3
4
5

This page intentionally left blank.