

1
2
3
4

ADDENDUM E
PROCEDURES TO PREVENT HAZARDS

1
2
3
4

This page intentionally left blank.

ADDENDUM E
PROCEDURES TO PREVENT HAZARDS

1
2
3
4
5
6
7
8
9
10

CONTENTS

E. PROCEDURES TO PREVENT HAZARDS.....E.5

E.1 Security RequirementsE.5

E.1.1 Security Procedures and Equipment.....E.5

E.1.2 WaiverE.5

1
2
3
4
5

This page intentionally left blank.

1 **E. PROCEDURES TO PREVENT HAZARDS**

2 The 400 Area WMU is designed and operated to minimize exposure of the general public and operating
3 personnel to waste. Shielding, control of toxic or dangerous material, safety and security procedures, and
4 structures are used to keep exposure within ALARA requirements. In addition, the 400 Area WMU is
5 designed to withstand accidents without undue risk to the health and safety of the general public and
6 operating personnel.

7 **E.1 Security Requirements**

8 Refer to Permit Attachment 33, Section 6.1, Security.

9 **E.1.1 Security Procedures and Equipment**

10 The 400 Area WMU is located within the 400 Area property protection area (PPA) of the Hanford
11 Facility and access is controlled by physical barriers, which complies with [WAC 173-303-310\(2\)\(c\)](#).
12 Signs stating *Danger-Unauthorized Personnel Keep Out*, or equivalent language, legible at 7.6 meters
13 (25 feet) or more, are posted near the entrance of each mixed waste storage area.

14 **E.1.2 Waiver**

15 Waiver of the security procedures and equipment requirements for the 400 Area WMU is not requested.
16

1
2
3
4
5

This page intentionally left blank.