



U.S. Department of
Homeland Security
**United States
Coast Guard**



Incident Report: Davy Crockett Emergency Response

March 12, 2011 Operations

No work on the Barge Davy Crockett Sunday. Operations resume 7 a.m. Monday, March 14.

On Saturday, divers completed another 6 dives, removing 4,650 pounds of bricks; this completes all brick removal for cargo holds #2 and #3. Approximately 17,792 gallons of oily water was pumped off as well. Topside work continues to focus on installing the equipment and fixtures needed to tow the stern section when it is re-floated.

On Friday, the Safety Zone around the Barge Davy Crockett was reduced in size to 200 feet in all directions from the vessel; this includes boom and support vessels. The Safety Zone is in effect for both stationary and moving on-water operations. There is also a no wake requirement for vessels transiting the area.

Also on Friday, dive operations continued to remove thick bunker oil, bricks and piping. Top-side work involved continued prepping of the stern for tow operations when it is re-floated. Approximately 10,000 pounds of brick and steel and 1,100 gallons of bunker oil/water were removed from the Davy Crockett on Friday.

Thursday's hull survey by divers revealed no surprises and confirmed that the vessel is sitting on the bottom as expected. After unloading approximately 84,000 gallons of oily water from four large storage tanks, the support barge Mark III returned and is alongside the materials barge Umpqua at the Davy Crockett work site.

No tar balls were found downstream of the Davy Crockett on Friday or Saturday. However, if anyone discovers what they believe to be tar balls in the river, they should contact the National Response Center hotline at 1-800-424-8802.

Last updated 3/11/11

Incident duration:	44 days
Personnel Currently Assigned:	68 state, federal response contractors
Injuries	0
Work and response vessels	16
Total Oil water mixture recovered to date	74,391 gallons*
Debris removed to date (e.g. metal, wire, wood)	673,639 pounds
Oil containment boom:	8,200 feet
Oil sorbent boom:	9,800 feet
Total recovery capability of skimmers:	336,924 gallons per day
Total waste oil storage volume:	160,725 gallons
Projected Maximum Worst Case Spill	64,500 gallons
Worst case spills potential	717,000 gallons

Samples analyzed to date (e.g. water, oil sediment)	116
Obligated costs to date	\$5.3 million
* This figure represents the amount of oily water mixture that has been recovered directly from the Barge Davy Crockett during response operations. An initial unrecovered release of an estimated 70 gallons of oil was documented on January 27, 2011 the day the vessel was discovered to be leaking oil.	

Incident Summary

A 431-foot flat-deck barge called the Davy Crockett is partially sunk on the shoreline of the Columbia River near Camas, Washington approximately 4 miles upstream of the Interstate 205 Bridge. The vessel has partially fractured into two sections and is leaking oil. Response crews and equipment are on-scene recovering the majority of the oil near the vessel as it leaks.

Davy Crockett History

The Davy Crockett is a former US Navy Liberty Ship that has been converted to a flat-deck barge. As with many aging vessels, ownership of the vessel has changed several times throughout the years. The most recent ownership change occurred in mid-2010. The vessel is anchored on the Columbia River, on Washington State owned aquatic lands.

In April 2009, due to concerns of fugitive oil sheen leaking from the vessel and the instability of the moorings, the US Coast Guard issued a *Captain of the Port Order* for removal of bulk oil, contaminated water and other hazardous materials. The order also required the vessel to be adequately secured to the shoreline to prevent it from becoming a hazard to navigation. The materials removed from the vessel included 2,200 gallons of a diesel/water mixture, 800 gallons of ballast water and 2,800 gallons of fuel oil.

Ecology's Environmental Reporting Tracking System identified several mystery sheens reported in this area of the Columbia River dating back to January 2010. These reports were investigated but no source was identified.

Recent Events Leading to Emergency Response

On the morning of January 27, 2011 Ecology began investigating reports from boaters on the Columbia River who were reporting scattered oil sheen in foggy weather. Ecology spill responders investigated by boat and identified an oil sheen stretching nearly 9-miles down river, and identified the Davy Crockett as the source.

An investigation is underway to determine the exact cause of the structural failure; however, metal salvage operations of the vessel appears to have initiated the release of oil from the vessel. Removal of deck steel compromised the structural integrity of the vessel resulting in the vessel fracturing into two halves. The bow section of the vessel is currently sitting on the river bottom next to the shoreline and the stern section has risen up to 30-feet in elevation. This structural instability of the vessel and safety concerns is making the complete assessment of oil products onboard impossible.

Incident Potential

The exact potential volume of oil still on board that could spill is unknown due to safety and access challenges. Total potential oil based on capacity of all liquid tanks is 935,000 gallons, but as the stern section is stabilized, responders will be able to accurately gauge how much oil actually remains in the vessel.

For up to date information, refer to the Ecology website at:

<http://www.ecy.wa.gov/programs/spills/incidents/DavyCrockett/DavyCrockett.html>