

From: [Schaffner, Larry](#)
To: [Labib, Foroozan \(ECY\)](#)
Cc: [Gersib, Dick](#); [Maurer, Mark](#)
Subject: Reference Typo in SWMPP
Date: Tuesday, February 07, 2012 8:04:16 AM

Hi Foorozan,

We just discovered a “reference typo” in the SWMPP. It appears in the section below:

6.1 Stand-alone stormwater retrofits

WSDOT has adopted a departmental budget structure with a specific category for retrofitting existing impervious surfaces in order to meet one of the requirements of Washington Administrative Code (WAC) 173-270-060. Construction of stand-alone BMP retrofits is accomplished through funding of WSDOT’s I4 Environmental Retrofit Project stormwater category. I4 stormwater BMP retrofits requires specific allocations through the Washington State Legislature with selection of individual stand-alone retrofit projects identified through WSDOT’s stormwater retrofit prioritization process, described in **Section 6.2** below.

The reference to *Section 6.2* is incorrect and should be changed to *Section 6.5*. Folks in our Program Management Section brought this to our attention as it was creating confusion. Can you please see to it that this correction is made as part of the permit mod? Thanks.

Larry Schaffner | WSDOT Environmental Services
PO Box 47332 Olympia, WA 98504-7332
☎ 360-570-6657 | 📠 360/570-6633