

Corrections and Clarifications to the *Stormwater Management Manual for Western Washington (February 2005) – Volume III*

Chapter 3

- p. 3-61, Proportional or Sutro Weir Design *correction*:

Equation 8 is incorrect, it should read:

$$Q = (C_d)(b)(\sqrt{2ga})\left(h_1 - \frac{a}{3}\right)$$

- p. 3-83, SSC-3 High Vehicle Traffic Areas *correction*:

“Road intersections with an ADT of $\geq 25,000$ on the main roadway, or $\geq 15,000$ on any intersecting roadway.”

Remove sentence and replace with:

“Road intersections with an ADT of $\geq 25,000$ on the main roadway, and $\geq 15,000$ on any intersecting roadway.”

Appendix III-D

- p. D-2, Procedure for Conducting a Pilot Infiltration Test *correction*:

“Applying a correction factor of 5.5 for gravelly sand in table 6.3 the design long-term infiltration rate becomes 2 inches per hour, anticipating adequate maintenance and pre-treatment.” “Table 6.3” should read “Table 3.9”.