

End View



Cross Section View

Collection pipe draining to Treatment Trench along north boundary from northeast property corner with placement location and depth based on bedrock depths

Groundwater Collection and Conveyance

NTS

Priceless Gas Cleanup Action Work Plan
Date: 4/15/2004 Figure 6

File: priceless\plgtreatmenttrench2004.FCW