

Figure 2. Depth Variation of PCBs in Deposit 1 Sediments Above Upriver Dam