



Photograph 13: Overview of Area 11 dense vegetative cover with shrubs



Photograph 14: Area 11 excavation showing high organic matter soil with wood chips.



Photograph 15: Overview of Area 12 showing dense vegetative cover.



Photograph 16: Overview of Area 13 showing dense vegetative cover.



Photograph 17: Overview of Area 14a showing moderate vegetative cover.



Photograph 18: Area 14a excavation showing sandy/gravelly soil.



Photograph 19: Overview of Area 15 showing dense vegetative cover.



Photograph 20: Area 15 excavation showing high organic matter soil.



Photograph 21: Overview of Area 16 showing moderate vegetative cover.



Photograph 22: Overview of Area 17 showing dense vegetative cover.



Photograph 23: Overview of Area 18 showing vegetative cover.



Photograph 24: Surface of Area 18 showing gravelly soil.



Photograph 25: Overview of Area 20 moderate vegetative cover with trees.



Photograph 26: Overview of Area 22 showing dense vegetative cover.



Photograph 27: Overview of Area 23 showing sparse vegetative cover.



Photograph 28: Overview of Area 24 showing lack of vegetation under the slab.



