

Hand Auger (2005)
Hand Auger (2003)
Hand Auger (1993)
Sediment Sample
Approximate Site Boundary
Abandoned Wooden Drainage Culvert
Buried Culvert

Figure 5a
Soil Sampling Locations
Hansville General Store

N W E S

0 30 60 90 120
Feet

DEPARTMENT OF ECOLOGY
State of Washington

N:\TCP\STAFF\IanM\09109_HansvilleStore_mark\mxd\figure5aRev2.mxd 1-11-2010 Source: Air Photo - Kitsap County 2007