



S:\10131\002\_R\SampleLoc032006.mxd



**Explanation**

- ⊕ Monitoring Well
- Direct Push Borings, February and March 2006
- Surface Soil Sample, July 2005
- ⊕ Test Pit, July 2005
- Previous Sample Location July 2000, November 2001
- - - Former Building
- ▭ MJB North Yard
- Cross Section Location



**SAMPLE AND CROSS SECTION LOCATIONS**  
 Upland Remedial Investigation  
 MJB Property, Anacortes, Washington

By: klb      Date: 03/24/06      Project No. 10131




Figure **7**