



Photo 13. Removing diesel tank.



Photo 14. Diesel tank after removal.



Photo 15. Pumping residual from gasoline tank.



Photo 16. Removing gasoline tank.



Photo 17. Gasoline tank.



Photo 18. Gasoline tank excavation after tank removal. Wooden cribbing/shoring left from original installation visible in sidewalls.