Photo 19. Northern USTs stockpile.

Photo 20. Gasoline tank excavation after final excavation. Concrete slab in bottom visible.

EMS
CONSULTANTS INC.
809 156TH STREET NE
ARLINGTON, WA 98223

PHOTO PLATE 4.
UST Decommissioning, Port of Seattle Terminal 106E, Building 6
4746 Ohio Avenue South, Seattle, WA
May 2004