



**Photo 1.** Removing asphalt over Bunker C tank.



**Photo 2.** Bunker C tank after asphalt removed.



**Photo 3.** Bunker C tank fill and piping access way.



**Photo 4.** Concrete hold-down slab over Bunker C tank removed.



**Photo 5.** Bunker C tank exposed. Pinnacle Geosciences, Inc. monitoring well DPB-3 at right in foreground.



**Photo 6.** Bunker C tank exposed. Broken storm line visible beneath loading dock at left. View looking north.