



Photo 7. Bottom of Bunker C tank excavation after tank removed. Small amount of product visible on water surface.



Photo 8. Bunker C tank after removal.



Photo 9. Diesel tank (left) and gasoline tank (right) after being uncovered.



Photo 10. Diesel and gasoline tanks uncovered.



Photo 11. Concrete pipe header suspected to be for removed propane tank.



Photo 12. Pumping residual from diesel tank.