Storm drain at head of inlet

Photo#52, 55, 56
Photos 53-54
Photo#45-46
Photos 47-51
Concrete

Photo # 45

Photo # 46: Close-up of previous photo

Photo # 47: Waste drums in sediments at EAA-2

Photo # 48: Close-up of waste material from previous photo. Slight petroleum sheen