

LOWER DUWAMISH WATERWAY  
 RM 2.0-2.3 EAST  
 Seattle, Washington

Figure 24  
 STORM DRAIN SYSTEM AND TANK LOCATIONS -  
 SHULTZ DISTRIBUTING

Base Map Reference: EMR Incorporated

Date:  
 5/21/08

Drawn by:  
 AES


10:002330WD1403\fig24



**ecology and environment, inc.**  
 International Specialists in the Environment  
 Seattle, Washington

References: 1976 Aerial Photo. Figure 2 of Dames & Moore, Soil Quality Assessment and Limited Asbestos and Lead Paint Survey, May 18, 1997. Figure 1 of Great Western Chemical Company, Northwest Corner Investigation, Terra Vac, August 2, 1999.

NOTE:  
A TOTAL OF ABOUT 42 MONITORING WELLS EXIST ON OR NEAR THE GREAT WESTERN CHEMICAL CO. SITE. THIS FIGURE ONLY SHOWS THOSE WELLS CITED IN TERRA VAC 1999 NORTHWEST CORNER INVESTIGATION REPORT AND WELLS LOCATED BETWEEN THE TWO SITES.



- LEGEND:**
- EXPLORATION LOCATION
  - B-1 AND B-2 TEMPORARY MONITORING WELL LOCATIONS BY GERAUGHTY & MILLER, MAY 1989
  - B-6 AND B-13 GROUNDWATER MONITORING WELLS BY HART CROWSER, 1990
  - B-22 AND B-26 THROUGH B-28 GROUNDWATER MONITORING WELLS BY HART CROWSER, 1992
  - B-53 THROUGH B-57 GROUNDWATER MONITORING WELLS BY TERRA VAC, 1999
  - MW1 THROUGH MW3 GROUNDWATER MONITORING WELLS BY AGI, 1999

— S — SANITARY SEWER LINE


PERCHLOROETHENE CONCENTRATION IN PARTS PER BILLION (ug/L)

TRICHLOROETHENE CONCENTRATION IN PARTS PER BILLION (ug/L)


VINYL CHLORIDE CONCENTRATION IN PARTS PER BILLION (ug/L)

GROUNDWATER SAMPLE COLLECTION DATE


ND = NOT DETECTED



|  |  |  |  |                          |
|--|--|--|--|--------------------------|
|  <p><b>ecology and environment, inc.</b><br/>International Specialists in the Environment<br/>Seattle, Washington</p> | <p>LOWER DUWAMISH WATERWAY<br/>RM 2.0-2.3 EAST<br/>Seattle, Washington</p> |  | <p>Figure 26<br/>GROUNDWATER ELEVATION CONTOUR MAP<br/>(DECEMBER 1999) - SHULTZ DISTRIBUTING</p> |                          |
|  | <p>Base Map Reference: AGI Technologies, 1999.</p>                         |  | <p>Date:<br/>5/21/08</p>   | <p>Drawn by:<br/>AES</p> |



S. WILLOW ST.



0 40 80  
Scale in Feet

- Vapor Extraction Vent
- Vapor Transfer Pipe
- Groundwater Extraction Well
- Groundwater Transfer Pipe



Base Map Reference: Floyd & Snider Inc. 2000.

LOWER DUWAMISH WATERWAY  
RM 2.0-2.3 EAST  
Seattle, Washington

Figure 28  
INTERIM REMEDIAL MEASURES - CASCADE COLUMBIA DISTRIBUTION  
(IN OPERATION AS GREAT WESTERN CHEMICAL)

|                  |                  |                       |
|------------------|------------------|-----------------------|
| Date:<br>5/21/08 | Drawn by:<br>AES | 10:002330WD1403/fig28 |
|------------------|------------------|-----------------------|

