

## **Appendix D-2**

**Hart Crowser 1989a: Report of Environmental Assessment—Parcel F, Soil and Groundwater Conditions, Evergreen Marine Leasing Property**

#3

RECEIVED

JAN 05 1993

DEPT. OF ECOLOGY

HTC



# HARTCROWSER

Earth and Environmental Technologies

**Environmental Assessment - Parcel F  
Soil and Groundwater Conditions  
Evergreen Marine Leasing Property  
Seattle, Washington**


**Prepared for  
Evergreen Marine Leasing**

March 22, 1989 - 8.5/11

J-2183-06


J-2183-06

# Site and Exploration Plan




DUWAMISH WATERWAY

# Tank Excavation Verification Sampling Plan



## Stockpiled Excavation Soil Samples




SP2-C Stockpile Sample Location and Number

 Material Exceeding TPH Cleanup Criteria


# Groundwater Elevation Contour Map

High Tide



# Groundwater Elevation Contour Map

Low Tide



DUWAMISH WATERWAY

