Department of Ecology

Water Quality Assessment for Washington

WQ Assessment Home | 2012 Search

Tools | Active: | Map Search | Layers | Help

~ Navigation Tools ~

- Pan
- Zoom In
- Zoom Out
- Zoom To Statewide Map View
- Zoom To Last Map View
- Zoom To Next Map View

~ Miscellaneous Tools ~

- Clear Selection And Graphics
- Identify
- Print Map
- NHD Reach Measure Tool



Identify Results

Assessment | Hydro | Boundaries

Latitude: 45.65686 **Longitude:** -121.02669 **Datum:** NAD83 HARN

29 listings found

Listing ID	Name	Parameter	Medium	Category	Waterbody ID
34872	COLUMBIA RIVER (LAKE CELILO)	Dioxin	Tissue	4A	1215974457119
18134	COLUMBIA RIVER (LAKE CELILO)	4,4'-DDE	Tissue	2	1215974457119
18149	COLUMBIA RIVER (LAKE CELILO)	Chlordane	Tissue	2	1215974457119

Water Quality Assessment for Washington Data Disclaimer Privacy Notice Contact Us

Copyright © 2012 Washington State Department of Ecology. All Rights Reserved.