Department of Ecology

Water Quality Assessment for Washington

WQ Assessment Home | 2012 Search

Tools | Active: | Map Search | Layers | Help



Identify Results

Assessment | Hydro | Boundaries

Latitude: 45.55646 **Longitude:** -122.21528 **Datum:** NAD83 HARN

1 listing found

Listing ID	Name	Parameter	Medium	Category	Waterbody ID
7887	COLUMBIA RIVER (BROUGHTON REACH)	Temperature	Water	2	1240014462974

Water Quality Assessment for Washington Data Disclaimer Privacy Notice Contact Us

Copyright © 2012 Washington State Department of Ecology. All Rights Reserved.