


Landau Associates

Hamilton Street Bridge Site
Spokane, Washington

Soil Boring, Test Pit and Monitoring Well Locations

Figure 4