

FIGURE 2-5
TRENCH RIM, PORTAL 2 AND BACKHOE TEST PIT SOIL SAMPLING LOCATIONS
LANDSBURG MINE SITE/RI/FS/WA

C:\DPT\9231000\147\57164 8-28-95 10:24

Golder Associates